19-20 Capi	tal Expenditu	re Needs				
5/30/2019						
		Priority Level 2				
Modifications according to OCR report at EHS	10,000		 Priority Level 1:			
Locker room modifications & install appropriate signage			Absolute necessity			
Change the slope of wheelchair ramps			Student - Staff safety			
Replace certain grab bars			Improve classroom environment			
			Priority Level 2:			
New EHS baseball stadium scoreboard	15,800		Necessary and impactful on large			
Current scoreboard is inoperable and can no			number of students			
longer be repaired			Improve district image			
RTU Replacements at EMS	45,000		Safety			
Two current RTU's are barely operable, parts are largely			Preservation of facility			
unavailable due to the age of units and they need to			Presentation of building			
be replaced			Presentation of building  Mitigation of future expenses			
Small vehicle replacement	50,000					
			Priority Level 3:			
Software upgrade HVAC units (EHS, RCE, SHE)	70,000	-	 Necessary	5500 Sec.		
Miss Took purphase	100,000					
Misc Tech purchase	100,000					
This is the standard annual purchase of tech		a 1 a 21 a 22 a 22 a 24 a 25 a 25 a 25 a 25 a 25				
equipment to replace old and obsolete hardware	150,250					
School busses (annual payment)	130,230					
This is to cover the annual payment for busses				APPROVATE AND A		
Soundproof RCE cafeteria		3,000				

Due to the proximity of the cafeteria to classrooms,		
the noise in the dining area disrupts learning		
Concrete repair RCE	3,000	
The poor condition of some areas of the concrete		
is a trip hazard and needs replacement		
School parking lot restriping	10,000	
This keeps clear lines of demarcation for vehicle parking.		
The curb painting for emergency vehicles and handicap		
parking to be clearly marked.		
Projection & Screen Replacement Cafetorium	12,000	
The EHS cafetorium's LCD projector is approximately 7		
years old and is now obsolete. This projector is used		
multiple times a year, some of which includes events		
for our community (for example annual STARS banquet)		
and it's become increasingly more difficult to view presentations		
& videos on the existing projector and screen.		
District parking lots and road surface repair	10,000	
Currently asphalt degradation is becoming worse and		
cracks are widening. If this continues moisture sepage		
under the asphalt will wash away the base underneath		
and will eventually create sink holes. The cost to repair		
at that time will be significantly more than today's		
Additionally, the road in back of EMS is riddled		
with deep pot holes, which damages both district		
and personal vehicles and hinders snow removal.		***************************************
Concrete repair EMS	15,000	
Concrete degradation has increased significantly over the		

past year and has increased the probability of causing					
a serious trip hazard. Additionally it portrays a poor					 
image of the district.					 
Districtwide carpeting replacement		25,000			 
Current old carpeting are trip hazards and portrays					 ***************************************
a negative image of the district.					
Football field refresh			9,500		
Plow equipment (ATV/UTV)		17 ) 10/10/10 10/10/10/10/10/10/10/10/10/10/10/10/10/1	12,000		
A Gator type vehicle that has the ability to plow			,000		
sidewalks, entryways and other areas we cannot fit a				110.000 - 00 1100 - 00 1 - 00 10 - 00 10 10 10 10 10 10 10 10 10 10 10 10	 
plow. In addition it gives operations the ability to use as	The second secon				
a grounds keeping vehicleduring other time periods.					 
New EHS football stadium scoreboard			20,600		 
Pave Superintendents parking lot and road base balance of a	dmin late		20,000		
Tave Superintendents parking for and road base balance of a		111 0 o 111 b			
EHS total gym floor resurface			44,000		· ** ** · · · · · · · · · · · · · · · ·
Total for each column	441,05	78,000	106,100		
Total Priority 1 and 2		519,050		-	
Total Priority 1 through 3			625,150		